

SITE INSPECTION REVIEW FORM

SITE NAME: CHAMPION INTERNATIONAL CORPORATION/RETAIL PKG. DIV.

ALIASES: \_\_\_\_\_

SITE I.D.#: NYD089756340

<u>ITEM</u>	<u>COMPLETE</u> <u>YES</u>	<u>?</u> <u>NO*</u>
SITE LOCATION (INCLUDING MAP)	<u>✓</u>	<u>   </u>
SITE BACKGROUND	<u>✓</u>	<u>   </u>
ENVIRONMENTAL SETTING (GEOLOGY, HYDROLOGY, METEOROLOGY, ECOLOGY + LAND USE)	<u>✓</u>	<u>   </u>
WASTE DESCRIPTION (PRESENCE + CONDITION OF WASTE + WASTE MANAGEMENT UNITS)	<u>✓</u>	<u>   </u>
LABORATORY RESULTS (CORRELATED TO SAMPLE LOCATION MAP)	<u>✓</u>	<u>   </u>
HRS PRE - SCORE (PRELIMINARY + PROJECTED)	<u>✓</u>	<u>   </u>
POTENTIAL FOR DIRECT CONTACT	<u>✓</u>	<u>   </u>
CONCLUSIONS + RECOMMENDATIONS	<u>✓</u>	<u>   </u>
REFERENCES	<u>✓</u>	<u>   </u>

HRS PRE-SCORE: PRELIMINARY SCORE = 30-73

PROJECTED SCORE = 35-72

305298



COMMENTS:

This is an L.S.I. candidate with a high priority. It is a shallow depth to groundwater and a large nearby population relies on the groundwater as a potable supply. More extensive sampling must now quantify the phthalates, solvents, metals, etc. detected in the S.I. There is no threat of contamination spread by the other migration routes.

REVIEWED BY: LARRY TANNENBAUM

DATE: FEB. 5, 1990

\*IF ANY ITEM IS LACKING INFORMATION PLEASE DESCRIBE IN COMMENTS